

Honda CR-V

VIN: SHSRE6740EU228727

Diesel

Generated on **2023-10-31 09:42**



Theft



Odometer



**Financial and legal
status**



Damage



+31

Data sources

We checked 900+ data sources in **35 countries**

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



We didn't find any records that the vehicle was stolen.

Here's what we checked:



Currently wanted as stolen

✓ No record found



Stolen in the past

✓ No record found

Current status unknown



Stolen in the past

✓ No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**

 Romania

 Finland

 Canada

 Slovenia

 Sweden

 Slovakia

 Italy

Odometer

Are there signs of mileage rollbacks or discrepancies?



Last known mileage: 238,168 km



1 mileage record found



2023

Odometer records

2023-10 **238,168 km**

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection passed 2023-10 in  **Latvia**

Legal



Technical inspection (also known as MOT)

Passed 2023-10

 **Latvia**

Has successfully passed
technical inspection



Scrap

✓ No record found

No record that vehicle was
marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Financial restrictions



Lease

✓ No record found

No data available on
outstanding loan or
finance agreement



Operating-lease

✓ No record found

No record of vehicle being
on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being
under unit-stocking
finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



No damage records found

amage records



casional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise hicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We ve a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Specs

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Honda



Model
CR-V



Body type
SUV



Model year
2015



Powertrain displacement
1.6 L



Powertrain power
88 kW (118 hp)



Fuel type
Diesel



Number of doors
5



Number of cylinders
4

Timeline

3 records found

The timeline of records for this vehicle

Records

2023-10

 Latvia



Ownership changed

The country (or state) indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2023-10

 Latvia



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

2023-10

 Latvia



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.



+31

Data sources

We checked 900+ data sources in **35 countries**